

[Document type] Drawing [Figure 1]

(1/14)




【図2】




[Figure 3]


(3/14)




[Figure 4] (4/14)




[Figure 5] (5/14)



(6/14)



(7/14)



[Figure 8]

(8/14)


If $(\omega > Th)$ then Instruct magnetic head to escape on the basis of a shock prediction Start escape timer else if $(\omega > Th/2)$ then Notify that operation mode has shifted to high risk mode Start high risk mode timer Endif

[Figure 9]

```
If (Escape timer times out) then If (\omega < Th/4) then Instruct magnetic head to return End if End if If (High risk mode timer times out) then If (\omega < Th/8) then Notify that operation mode has shifted to normal mode End if End if
```


[Figure 10]

(9/14)




[Figure 11]


(10/14)



(11/14)




(12/14)



[Figure 14]

(13/14)



[Figure 15] (14/14)

